




Switcher bumping and module situation

- ▷ Bumping (UBM process) causes problems with the new Switcher
- ▷ On one pad – the substrate pad – and only on this pad
 - ↳ Very little or no UBM deposition
- ▷ Main difference to old Switcher
 - ↳ Different passivation ($1\mu\text{m}$ Nitride/Oxide $\leftrightarrow$ PI)
 - ↳ Guard ring of the chip exposed, connected to bulk



→ Different electrochemical potential causes reduced UBM growth on substrate







4 modules assembled

▷ W31-IB, W31-OB, W31-IF

↳ DCDB4.2 (final), SWB2.1 (final, repaired bump), DHPT1.1

▷ W31-OF

↳ DCDB4.2 (final), SWB2.0 (last samples of the old version), DHPT1.1



▷ Flip Chip without any anomalies


↳ Switcher generally not prime grade due to problems with bumping (see next slide)

▷ SMD, Kapton attachment as usual


"fishy" Switchers, though tested okay

Modul W31-IB

Switcher 1



Folie 3




Ausrichtung des Moduls
X-Rayanalyse, 02.07.2013, Berlin
Kurzschluss im Ausgangszustand
Nicht entfernbare Material (SW 1 und 4)

Belle Pixeldetektor

Modul W31-IF

Switcher 5




Leiterbahn beschädigt



X-Rayanalyse, 02.07.2013, Berlin

Belle Pixeldetektor


Modul W31-OB1




Switcher 2



Switcher 3



Switcher 3



Switcher 3


:- SWBs show imperfections, scratches
:- flip chip was done, since the tests on chip level were positive

:- detailed xray inspection after FC showed no anomalies (apart from the Au stud bump)




Folie 7

Test Assembly of SWBs to bond adapter

- ▷ Adapters assembled for SWB testing on hybrid level
 - ↳ Three adapters assembled
 - ↳ One assembly done with bad chip (bumping problems)
- ▷ Cross-section




- ▷ 80 μ m balls $\rightarrow$ too much solder
 - ↳ Ongoing balling with 60 and 70 μ m balls






Test Assembly of SWBs to bond adapter

- ▷ Adapters assembled for SWB testing on hybrid level
 - ↳ Three adapters assembled
 - ↳ One assembly done with bad chip (bumping problems)
- ▷ Cross-section



- ▷ Delamination between SWB Alu and Ni?
 - ↳ Not certain if is this real
 - ↳ Could be due to contamination before UBM....



Batch „Persy1“: DCDB4.2, SWB2.1 (Pactech bumps), DHPT1.1


- ▷ W31-IB and W31-OB:
 - ↳ JTAG configuration fails as soon as the Switchers are in the chain
 - ↳ DCD, DHPT okay

- ▷ W31-IF:
 - ↳ JTAG configuration okay
 - ↳ See effect of bad substrate bump on the Switchers (3/6 SWBs not functional)


- ▷ W31-OF: **(SWB2.0)**
 - ↳ JTAG okay
 - ↳ → Philipp's report

Bumping on "wafer level" at IZM


- ▷ Assemble a "wafer" (glass) by pick-and-place of Switchers to support with alignment marks
 - ↳ Accuracy good enough for 150 μ m pitch, subsequent wafer level lithography possible
 - ↳ Possibility to apply standard technology bumping by electro-plating




Sputter Etching and Sputtering
of the Plating Base / UBM




Electroplating of Cu and PbSn



Spin Coating and Printing
of Photoresist



Resist Stripping and wet Etching
of the Plating Base





Reflow


- ▷ Tests run at IZM was positive, 24 bumped chips delivered

SwitcherBv2.1 bumped at IZM

- ▷ After seed layer deposition and lithography




- ▷ The bumped chip after reflow



BELLE II- Switcher tests

Switcher Chips	Read JTAG ID	Bias Current	Boost Current	64 HV-channels
18	✓	✓	✓	✓
1	✓	✓	✓	✗
5	✗	✗	✗	✗



1. Single Line
Distance: 3.69 μm

2. Single Line
Distance: 2.76 μm

4. Single Line
Distance: 23.28 μm

MPG-HLL
14.12.2016 10:36
100x: 94 μm x 59 μm


- ▷ New modules (batch "persy2")
 - ↳ DCDB4.2, DHPT1.1, SWB2.1 (IZM bumps)
 - ↳ W37-IB, W31-OB2
 - ↳ Expected to be back from Flip Chip next week
 - ↳ Exchange the IB/OB with DCDB4 for the beam test

- ▷ W31-IF, W31-OF now under test, other possible candidates for beam test,

- ▷ ~450 SWB2.1 at IZM for bumping
 - ↳ Complicated, expensive and lengthy process
 - ↳ Expected back for probe station testing mid/end February

Backup

Residues? Photo resist?



Not clear ... (from adhesive tape??)

