Status Infrastructure D.07

D.07 close to fully equipped, cleaning procedure established



D.07 access



- DACHS is working, but access is currently still with key ...
 - ► We need a door handle or electronic latch asap to abolish key management issues
- Air conditioning



- Commissioned at end of March: ΔT ok so far, although the flow is too high
- Recent down time due to controller failure: 5d
 - ▶ <u>Important:</u> we need short notice access to make changes to T and flow settings for laser optimization purposes from now on!!!
- D.07 smoke detectors:
 - So far not hooked up to safety loop ...
 - Under way now



Status PP-Laser Installation

- PP-Laser assembly and commissioning
 - Pre-assembly: ca. 75%
 - Seeder, Front-End, Pump-Amplifiers were commissioned independently.
 - ► Long term data of combined performance are still not available due to lack of diagnostics and logging capability so far.



- Seed beams routed to NOPA
- Pump beam routing to NOPA is starting now



Beam delivery

- Shutters, beam pipes, vacuum installed
- 800nm alignment laser beams to FXE and SPB through vac. pipe by 12th May.



Procurement of conversion hardware for Instruments started.

Synchronization

- RF-Sync is operative and stability was improved over the past months in cooperation with WP18.
- HOWEVER, potential show stopper: on 10th May we were told, that a timing reference to x-ray bursts will not be available by September (first experiments).



- ► Link at sync sub-hutch: October 2017
- ► Installations in sub-hutch: October + X months
- WP18 is evaluating if bridging solutions are feasible.



Status Controls

- Certain linear and rotation stages (stepper motors) started to function this week. Some remaining issues, e. g.
 - specific stages don't work yet



- units for the rotation stages are in mm and not in degrees
- KARABO is improving in general (e. g. support, stability, sensors, cameras), although still with head room, e. g.
 - poor stability of image processors.
- We still have memory and CPU issues, which lead to issues elsewhere in the system...
- Both X2 timers are now synchronized to each other and the laser trigger schemes are now implemented in the hutch







