



PXD Slow Control

Phase 2 / Phase 3 / PXD 2020



Michael Ritzert

michael.ritzert@ziti.uni-heidelberg.de


Belle II PXD Workshop

DESY

08.10.2018

Phase 2

Setup



- 63 GB of archiver data.
 - Quick extrapolation:
 - × 14 ($\frac{1}{2}$ year \Rightarrow 7 years)
 - × 10 (4 modules \Rightarrow 40 modules)
 - ~ 9 TB for phase 3
 - Half the previous estimate.
- 570 MB of message log data.
- 200 configDB commits.
- Everything backed up to KEKCC.

- Start of phase 2: The shifter had to manually ramp up the PXD module by module.
 - PS firmware/IOC implementation failed with too many commands in a short time.
- PS firmware / IOC finally updated in June.
 - First attempt in February failed due to very strict interlock condition in the IOC.
 - The root problem (lost UDP packets) is still present, but now ignored until it happens too frequently.
 - Not deadly, but I'd like to understand why. Remember: It never shows up in my lab.
 - Hardware to be analyzed towards possible improvements (differences between PHY datasheet and implementation).
- Since then: Ramping all four modules in parallel.

We managed to successfully test all interlocks... ;-)

- IOC to PS unit:

- IOC doesn't send heartbeat often enough \Rightarrow unit shuts down.
- Most likely reason: Overload of the pxdgw1 system (IOC + archiver)
 \Rightarrow PS IOC is not scheduled frequently enough by the OS.
- Happened most frequently on Sunday mornings (RAID check creates additional load) \Rightarrow Supports this interpretation.
- For commissioning: The archiver is now on pxdgw2
 \Rightarrow So far no reported occurrence despite running more units.

- PS unit internally:

- Firmware reported that command processing takes too long, shut down.
- Always happened at the end of the rampdown sequence
(many commands in short time).
- Only happened on two days (in a row)!
- Totally unclear. To be debugged if it becomes reproducible.

- Run Control was integrated with Belle II from the start of phase 2.
 - A few confusions generated on the NSM2 side:
Inconsistent state displays.
 - Actual RC operation not affected.
- Power Supply Control integration happened in June.
 - New PS firmware deployed
⇒ modules could be ramped in parallel.
 - PXD operation by Belle II shifter possible unless
 - we went into ERROR
 - the shifter tried to go via OFF.