





Ladder Assembly

Series gluing of 11 ladders using
improved gluing procedure



View of stiffeners right after insertion
Still possible to do (manual) corrections



Review



Review held end of February

Reviewers: Jelena Ninkovic, Ariane Frey, Igor Konorov, Hans Krüger, Christian Irmeler

Participants: Carsten Niebuhr, Laci Andricek, Karl-Heinz Ackermann, Hans-Günther Moser

Many proposals and recommendation which were implemented

Follow up Report July 8, Final Meeting July 23.

Production started already in June, since critical issues were resolved by then.

Unused equipment removed

Better access to alignment setup


ESD mats on floor and tables

No loose cables etc (easier cleaning)

2x cleaning/week



Overall view




Assembly workspace (flowbox)



Alignment setup, Mitutoyo CMM



Inspection



New Features



Control of glue dispensing
using UV light
(with bare eye even better)




Additional guiding pin
(red) to reduce roll and
pitch of lifter


=> Exact positioning of
stiffeners

Raspberry Pi camera for
control of stiffener insertion

Life picture after insertion

Enables manual corrections





Work Flow

K. Ackermann

Klebewoche für Ladder.docx

14.08.2019

Ladder Klebungen (Einteilung für 2 Klebungen pro Woche [v3.0])

Wochentag	Montag	Dienstag	Mittwoch	Donnerstag	Freitag
08:00-10:00	Ausbau		Ladder härtet aus	Ausbau	Reserve
10:00-11:00	E-Messung	Reserve		E-Messung	L-Klebung
11:00-12:00	K-Messung			K-Messung	
13:00-14:00	E-Messung	Reserve		E-Messung	Ladder
14:00-16:30	Reserve oder L-Klebung	L-Klebung		Reserve oder L-Klebung	härtet aus

Gluing procedure needs ~1:40h (plus time for module test & inspection)


Curing time >40h (24h sufficient)

1h to take out and pack plus survey ('K-Messung') and electrical tests ('E-Messung')

Can comfortably glue and test two ladders a week


We want to keep to 'gluing campaigns' with continuous gluing over several week

Most efficient in terms of organisation, setting priorities, sharing manpower with other projects and especially routine of operators.




Ladders glued

#	Nr	fwd	bwd	grade	elec. Test	comment	
	1LK 42	W02 OF1	W03 OB1	B	ok		
	2LK 43	W09 OF1	W09 OB1	A	ok	cracked during inspection	
	3LK 44	W32 OF2	W32 OB2	A	ok		
	4LK 45	W33 OF1	W42_OB1	A	ok		
	5LK 46	W33 OF2	W46 OB2	A	ok		
	6LK 47	W46 OF1	W45 OB2	A	ok		
	7LK 48	W13 OF2	W46 OB1	A	ok		
	8LK 49	W08 OF2	W08 OB1	A	ok		
	9LK 50	W46 OF2	W08 OB2	A	ok		
	10LK 51	W45 OF1	W42 OB2	A	ok		
	11LK 52	W43 OF1	W33 OB1	A	ok		



Run out of tested modules August 30.




Alignment

dH (up)	dH(down)	gap(up)	gap(down)	dx(up)	dx(down)	
15,4	-6,2	115	114	5,7	4,7	
30,8	-0,5	116,8	117,5	2,8	1,7	
-4,9	-24,1	122	123,4	-3	-2,8	
8,3	-3,4	120,2	114,8	2,3	3,4	
13,8	0,8	114,2	111,9	0,2	0,3	
15	-4,3	119,7	115,4	0,7	0,1	
39	16,9	114,8	114,4	3,3	0,7	
27	6,2	119,8	113,6	-2,5	-1,3	
29,5	2,9	120,2	118,2	-6,1	-0,4	
25,5	8,9	116,9	118,1	0,7	0,4	
14,4	-13,3	121,8	119,2	-5,7	-5,6	
19,44	-1,46	118,31	116,41	-0,15	0,11	Mean
11,74	10,51	2,72	3,10	3,60	2,67	RMS


Up: at small balcony

Down: at wide balcony




All figures in μm


dH: step between modules




gap: glue gap between Al




dx: lateral displacement





LK 42: glue did not spill out, difficult to judge which area is glued
(nevertheless, the joint is well glued)




LK 51: Excess glue essentially visible everywhere (tolerances of slot)

High speed links of our ladder setup were unstable: not possible to test ladders reliably after gluing. Indirectly this lead to a loss of one ladder during inspection (LK-43, hit by a microscope lens which detached itself (fixed)


Had to use module setups for testing => no module characterization in parallel


Turned out to be a grounding problem in the ladder setup (two branches), understood, ifxed (need DHH)



One module (W12_OF1) failed the electrical test before gluing (high currents). Turned out that had a crack.

Had already been tested im May and was ok then. Stored with other modules and not touched since. Not known what happend.





Summary



Assembly procedure changed:

sensor surface not touched,
stiffeners inserted from below using a tool

Method and facilities were reviewed (incl. follow up)

(Most) suggestions realized

Test with dummy (1 simple dummy, 3 Kapton dummies)

Some improvements needed
last assemblies very successful

11 ladders successfully glued, no loss related to gluing
(however: one ladder lost during inspection)

Gluing procedure needs 1:40h (plus time for module test & inspection)

Curing time >4h

Can comfortably glue two ladders a week