

# DHH Status

**Igor Konorov**


Institute for Hadronic Structure and Fundamental Symmetries (E18)

TUM Department of Physics



Technical University of Munich

Belle2 PXD Workshop


January 20-th, 2020



# DHP Links' Light Power



# DHP Links' Light Power



# Changes of Gated Mode in DHC

## ➤ **Previous implementation**

- Two state machines to generate GATE and Trigger VETO
- Two sets of parameters to define start and length
- Time relation between frames and injection signal could cause resynchronization at start and stop of the state machines

## ➤ **Current version**

- One state machine for both signals with programmable offset and length for TRIGGER VETO

# Observed Problems

## ➤ **Missing trigger(event)**

- It caused synchronization error of event building in ONSSEN due to Round-robin algorithm of event distribution in DHC
- One Hub was affected (5 detectors)
- DHC detected consecutive event number error
- Possible origin of the problem FTSW port or DHC
- Action :
  - Round-robin algorithm modified to use FTSW event number for evaluation destination number instead of local event number
  - Installation of VME DHH module to centralize trigger distribution to entire PXD

## ➤ **Missing start of row error**

- Error reported by ONSSEN
- No errors in DHE and DHC
- Possible it is caused by DHH-ONSSEN link errors

# Observed Problems

- **Blown up fuse of Cross-switch caused long stop of PXD**
- **Instability of UCF links**
  - after power up some links are not established, mostly affects DHI modules

# Problem Analysis , Yamada's slide

## DAQ DOWNTIME IN THE LAST 11 DAYS( RUNS IN DEC.)

12/1/2019-12/11/2019

Sub-system	Total downtime [min]	# of troubles	Ave. downtime [min.]
DAQ	563.8	87	6.5
TRG	358.3	33	10.9
CDC	145.5	23	6.3
PXD	137.7	12	11.5
TOP	54.2	7	7.7
ARICH	9.0	2	4.5
KLM	9.0	2	4.5
Accelerator	331.6	12	27.6

The last week in 2019a run in June

subsystem	Downtime[ min.]
TRG	227.2
DAQ	161.7
TOP	150.3
CDC	88.8
ARICH	30.8
PXD	20.3
ECL	15.1
KLM	4.5

## 4. PXD troubles

- Due to high-occupancy, link lost, strange DQM plots etc.
- Basically, needs experts' help to fix

Date	Downtime [min.]	Symptom
12/09-23:45:35	50.4	PXDRC error (no data for backward modules according to PXD expert)
12/10-00:54:04	38.3	To fix the PXD data lost problem
12/02-23:51:05	9.8	to cure the high occupancy module
12/09-02:00:18	9.8	PXD sensor problem
12/02-23:20:58	6.8	to cure the high occupancy module
12/09-05:11:28	6	PXD Common Mode in DQM is red
12/02-23:28:30	3	to cure the high occupancy module
12/03-00:01:37	3	PXD Common mode plot in DQM is red
12/03-00:24:12	3	PXD DQM turned red
12/07-02:51:47	3	PXDRC ERROR(zero efficiency)
12/09-04:39:52	2.3	PXD CommonMode in DQM is red
12/10-00:47:17	2.3	PXD lost some data links



# Error Analysis

- No PXD data from DHC30
  - 9.12 at 11:50pm, lasted 2 hours
  - Problem was solved by DHH power cycling
  - Origin of the problem
    - Readout Mode was set to local run. Detector produced MemDump data.
    - Caused by crashed script and left DHH in wrong mode
    - Wrong DHH status is not be propagated to ALARM
    - Slow control should handle such case

# After Run Activities at KEK

## ➤ Investigation of problem with DHP link


- During autumn run after IPMCs' installation one DHP link went down and solution was to reconnect the detector to spare DHE by reconfiguring cross-switch
- Problem was traced to broken optical receiver socket in DHH RTM module
- Spare DHH RTM installed instead

## ➤ 5-th fully functional DHH system installed as spare

# After Run Activities at KEK

## ➤ Test of DHH-ONSEN links

- Individual optimization of DHC TX parameters to minimize error probability



# Activity before Start of Run

- **Installation of second cross-switch as spare**
  
- **Installation of VME DHH module**
  - FTSW => VME DHH => 5-th DHH
  - Test of centralized trigger distribution
  
- **Test of ONSSEN links**
  - 5-th DHH will be connected via

# Preparation for Full PXD Installation

- **Production of 22 DHE/C modules**
  - Completed and all modules tested
  - 127MHz oscillators to be mounted
- **2 spare DHH systems were shipped back from KEK to TUM, thanks to Shuji**
- **3(4) DHH systems will be prepared for installation at DESY**
  - Will be ready in April
  - When to be installed at DESY?
  
- **To be done at KEK**
  - Increase DHH rack size, the high is too low to fit all equipments
  - Install second ATCA shelf with 6 slots
  - Install one(two) online server on top of Belle2
  - Install Ethernet switch for new equipments
  - third cross-switch

# Conclusions and Outlook

- Clamp fixed problem of DHP optical links' instability
- Few DHH stability issues were improved and few more to be improved
- Improving propagation of status information within slow control to be improved in order to maximize up time
- DHH worked reliably during last run
- Closer look at full PXD preparation and installation is required

THANK YOU