

WHAT CAN GO WRONG ...


SOME EXAMPLES



DISCLAIMER

- Designing a large (silicon) detector for particle tracking or identification is a very complex business
 - Many very nice examples exist
 - Also some examples of failures
-
- Idea of this talk: some stuff you don't find in textbooks
 - Collection of failures might give the impression of overall incompetence
 - Overwhelming majority of detectors run like a chime
 - Unbelievable effort to get large accelerators and experiments in a global effort to run so nicely
 - Even sociologists are interested in how we do this ...


Some bias in the selection of detectors and examples based on my experience, my friends and other factors ...






PROBLEMS IN OVERALL CONCEPT

D0 WITHOUT INNER TRACKING MAGNET

- D0 Experiment at Tevatron constructed to study proton-antiproton collisions
- **Top quark discovery** in 1995 together with CDF experiment
- Original design for Run I: no magnet for tracking
 - “Focussing on parton jets for deciphering the underlying physics than emphasis on individual final particle after hadronisation”
 - Very compact tracking system
 - Uranium-liquid argon calorimeter for identification of electrons, photons, jets and muons
- Effect of low momentum charged particles greatly underestimated resulting in analysis difficulties.



Run II system included a silicon microstrip tracker and a scintillating-fibre tracker located within a 2 T solenoidal magnet.





Top quark discovery

ZEUS TRD

- Zeus Transition Radiation detector for electron identification.
- Aim: h/e rejection ratio of about 10^{-2} for electron tracks embedded in jets (1 - 30 GeV/c).
- However - central tracking detector (wire chamber) had 2cm end-plate for wire fixation
 - Electrons 100% probability to shower and thus were not present in showers anymore
- Reason for mishap: no proper Monte Carlo simulation tools available at time of detector design
 - TRD used for Here Run I Replaced by Straw Tube Tracker for Run II

Lesson learned:
Monte Carlos simulations
should include everything




UNEXPECTED IRRADIATION FAILURE

RADIATION DAMAGE IN SILICON

- Radiation damages the silicon on atomic level significantly leading to macroscopic effects.


- **Surface effects:** Generation of charge traps due to ionising energy loss — Total ionising dose, TID **(problem for sensors and readout electronics)**.

- Cumulative long term trapping of positive charge
- Increase of leakage current and oxide breakdown



- **Bulk effects:** displacement damage and build up of crystal defects due to non ionising energy loss (NIEL) **(main problem for sensors)**.

- Unit: 1MeV equivalent n/cm²



Defects composed of:
Vacancies and **I**nterstitials

Compound defects with impurities possible!

- **Transient effects:** Radiation induced **errors in microelectronic circuits**

- caused by passing charged particles leaving behind a wake of electron-hole pairs
- single event upsets, single event latch-ups,


Generations of scientists worked on understanding failures connected to radiation damage and how to mitigate the effects - however ...

CMS DC-DC CONVERTER

during running

- During 2017 new pixel detector installed in CMS with DC-DC converter for powering
 - After few months: ~5% of deployed converters failed.
 - During winter shutdown: another ~35% of converters were found partially damaged
- Extremely difficult to identify problem - over months multiple tests conducted
- Found strong correlation between radiation background and failures, as well as the functional sequence necessary for the damage to happen.
 - Damage caused by TID radiation damage opening a source-drain leakage current in **one** transistor in Feast2.1 chip
 - High-voltage transistors can not be designed in an enclosed layout to prevent this problem

DC-DC in a nutshell:
transfer energy into detector with higher voltage/lower current and transform just before the load to operation voltage



Feast2



Consequences for operation

- lower input voltage helps
- stop disabling the output

TID BUMP


Surface effects: Generation of charge traps due to ionizing energy loss (Total ionising dose, TID)
(main problem for electronics).

- The leakage current is the sum of different mechanisms involving:
 - the creation/trapping of charge (by radiation)
 - its passivation/de-trapping (by thermal excitation)
- These phenomena are dose rate and temperature dependent!
- Charge trapped in the STI oxide
 - +Q charge
 - Fast creation
 - Annealing already at T_{amb}
- Interface states at STI-Silicon interface
 - -Q for NMOS, +Q for PMOS
 - Slow creation
 - Annealing starts at 80-100C




ATLAS IBL TID BUMP

- Steep increase in power consumption of IBL during operation increasing the temperature
- Effect of total ionising dose on front-end chip FE-I4B
- Caused by the effect of TID on NMOS transistors:
 - Leakage current was induced by positive charge trapped in the bulk of the shallow trench isolation (STI)
 - Temperature and voltage depending



during running



Mitigation plan:

- Operating temperature was increased from $-10^\circ C$ to and $10^\circ C$ then decreased to $5^\circ C$.
- Digital supply-voltage was decreased to from $1.2 V$ $1.0 V$ until TID approached more than $4 MRad$.

"LOW TECH" FAILURES

WHAT IS “LOW” TECH ?

- In particle physics experiments almost everything is **high tech**
 - Need extreme reliability
 - Radiation tolerance
 - Precision
 - Mostly running longer than originally planned
- However - some areas considered as “low tech” and people (and funding agencies) don’t like to invest research money into those areas
 - Cables for powering
 - Power plants
 - Cooling
 - Data transfer (optical and electrical)
 - Non sensitive materials (mechanics)
 - Glues
 -


what are other words for low-tech?



simple, unsophisticated, basic, dolly, foolproof, onefold, elementary, simpler, crude, rudimentary



For particle physics experiments this is not true !






WIRE-BONDS AND WIRE BREAKAGE

PROBLEMS WITH WIRE BONDS (CDF, DO)

during running

- Very important connection technology for tracking detectors: wire bonds:
 - 17-20 μm small wire connection -> terrible sensitive
- Observation: During synchronous readout conditions, loss of modules (no data, Drop in current)



- Tests revealed:
 - Bonds start moving due to Lorentz Force in magnetic field
 - Wire resonance in the 20 kHz range
 - Current is highest during data readout
 - Already a few kicks are enough to get the bond excited


Implemented “Ghostbuster” system which avoids long phases with same readout frequency

OPAL MVD 1994

- OPAL MVD ran for a short while without cooling water flow.
- Temperature of the detector rose to **over 100°C**.
 - Most of the modules to fail or to be partially damaged.
- Chain of problem causing damage:
 - MVD expert modified the control/monitoring software between consecutive data taking runs.
 - Inserted bug which stopped software in a state with cooling water off but with the low voltage power on.
 - Stopped software also prevented the monitoring of the temperature from functioning
 - Should have been prevented by additional interlock but that was also disabled....

Lucky outcome:

- Damage was mostly melted wire bonds
- Detector could be fixed in winter shutdown






Mitigation plan:

- new and more rigorous interlock system that could not be in a disabled state during data taking conditions.
- rule was implemented that prohibited software modifications between consecutive data taking runs.

ATLAS IBL - WIRE BOND CORROSION

- Additional pixel layer for ATLAS installed in 2015
- Five months **before** installation: corrosion residues observed at wire-bonds after cold tests (-25 C)
- Severe damage of many wire-bonds
- Residue showed traces of chlorine: catalyst of a reaction between Aluminium (wire-bonds) and H₂O (in air)
- Origin of chlorine in system never fully understood




- Emergency repair and additional staves from spare parts


during production

MORE WIRE BOND WRECKAGE

- During CMS strip tracker production quality assurance applied before and after transport
 - Quality of wires is tested by pull tests (measured in g)
- Wire bonds were weaker after transport with plane
- Random 3.4 g NASA vibration test could reproduce same problem
- Problem observed during production -> improved by adding a glue layer
- No further problems during production



during production





COOLING DAMAGES

WATER DAMAGE IN TRACKER ...

- H1@HERA FST in 2004
- Imperfect crimp + hardening of plastic (age, irradiation) => water leak
- Water condensation => damage
- Tracker segment had to be rebuilt




during running



ATLAS PIXEL TUBE CORROSION


during production

- Cooling tube of current pixel layers were supposed to be very light in material
 - Bare pipe material (Al)
 - Ni plating used to allow for brazing of the pipe fittings
 - No proper drying procedure → water
- Water triggered corrosion process in the aluminium pipes.
 - Corrosion was due to galvanic process where water and traces of halogen (like Cl) acted as electrolyte.
 - Effect of the galvanic corrosion led in some cases to holes in the pipe.



Six months delay in schedule

- Repair the 43 loaded staves with a pipe-inside-the-pipe
- Production of new staves with new Al compound and laser welding
- Repair of bare staves (~100)



The background of the slide is a light blue surface covered with faint, handwritten mathematical notes and diagrams. The notes include various equations, such as $P_+ = \frac{M_{1,2}^3}{M_{1,2}}$ and $P_+ = \frac{\Delta}{\omega_0} \approx \frac{\Delta}{\omega}$, and several graphs showing curves and axes. Some diagrams include circles and lines, possibly representing geometric or physical relationships. The handwriting is in black ink and is somewhat faded, serving as a decorative backdrop for the main text.

OTHER PROBLEMS AND FAMOUS PROBLEMS

ATLAS IBL STAVE BOW


during commissioning

- Distortion depending on the operating temperature was observed.
- Caused by a mismatch between the coefficients of thermal expansion (CTE) of a bare stave made with the carbon foam and the flex attached on the bare stave.
- Maximum more than 300 μm at $-20\text{ }^\circ\text{C}$ with respect to the nominal position at the room temperature.




Mitigated by temperature control at the level of 0.2 K and the regular alignment correction in the offline reconstruction

multiplied by a factor 20



CABLE PROBLEM WITH PRESS COVERAGE


- Oscillation Project with Emulsion-tRacking Apparatus — **OPERA**: instrument for detecting tau neutrinos from muon neutrino oscillations
- In 2011 they observed **neutrinos** appearing to travel faster than light.
 - Very controversial paper also within collaboration



The top 10 biggest science stories of the decade

- Kink from a GPS receiver to OPERA master clock was loose
 - Increased the delay through the fibre resulting in decreasing the reported flight time of the neutrinos by 73 ns,
 - making them seem faster than light.




After finding the problem, the difference between the measured and expected arrival time of neutrinos was approximately 6.5 ± 15 ns.



MAYBE MOST FAMOUS DAMAGE

during commissioning

- Underground water Cherenkov detector with 50,000 tons of ultrapure water as target material
- Nov 2001: One PMT imploded creating shock wave destroying about 7700 of PMTs



- Detector was partially restored by redistributing the photomultiplier tubes which did not implode.
- Eventually added new reinforced PMTs


LESSONS LEARNED ?

- Spend enough time on simulating all aspects of your detector with ALL materials implemented
- Don't underestimate the "low tech"
 - Cables
 - Cooling
 - Mechanics including FEA
 - Radiation damage of non-sensitive materials
 -
- Make sure the overall timeline is not completely crazy (tough job)
- When mixing materials — ask a chemist once in a while
-

This project is super urgent.
I need it like
yesterday!



info@mool.in



Solving and preventing these kind of problems is also part of the fascination of detector physics!!

