ARES Operation Meeting

Summary of week 37 / 2023

Max Kellermeier, on behalf of the ARES crew





Summary of week 37


Achievements

Difficulties

Mon. 11 th Sep	Tue. 12 th Sep	Wed. 13 th Sep	Thu. 14 th Sep	Fri. 15 th Sep
	 Beam setup for eCT beamtime Initial eCT measurements Investigations of Gun issues 	 Gun water temperature and flow rate investigations → finally solved eCT studies continued with stable beam, 2D scans 	 Manual rotational scans with automated 2D scan for full 3D reconstruction Long 2D high res. scan in the evening 	 3D scans continued High res 2D slice scan, i.e. rotational and horizontal scan
Gun modulator unstable (operational for ~1h)	 Gun modulator interlock overnight TWS2 in fault state 	TWS2 in fault state	Beam jump by 0.5mm on Timepix detector	
Tunnel openTunnel closed in the late afternoon				Gun conditioning over the weekend

Electron CT

Recap from last week



- Mouse phantom scanned with low charge (< 10 fC) beam
- Scattering detected with TimePix3 detector
- 2D scans: translational stages in x and y
- 3D scans: additional rotational stage

Synchronization procedure:


Scan always start at aluminum base plate

 onset when moving into the gap between aluminum and mouse

Beam setup for eCT


Tuesday


- Low charge beam (0.4 pC) transported to FL section, imaged on FL.A1
- Charge decreased by laser attenuator, beam position and size monitored with TimePix
- All our diagnostics blind:
 - T-ICT lower limit is 12 fC
 - Photobeam on FL.A1 hardly distinguishable from dark current



Wednesday: 2D scans


- Issues with data interpretation delivered by Timepix detector
- "Workaround necessary to analyse data"






Thursday: Manual 3D Scans

- 2D scans with manual rotations in between
 - → Time consuming
- Issue with beam jump (0.5mm) after about 75% of the measurement
 - Continued measurement
 - Beam jump corrected
 - All 2D scans repeated which where conducted after the jump
- Automated 3D scans prepared; to be tested in future
- High resolution scan in the evening




Friday: 3D scans

- Resolution from Thursday's 3D scans not sufficient → repeated with smaller ROI (same number of data points)
- High resolution slice scan: 1D scans along x-axis at slow stage velocity, repeated at more angular positions (automated with scan tool)



Gun Modulator Interlocks

- Event logs: "Interlock TI\DoorSts\Input missing" → Event log messages are outdated (old settings from Pitz modulator) and have no meaning for our modulator
- Tested gun water temperature:
 - (TUE) first due to detuning of gun operating at lower gradient
 - (WED) Later to trigger water temperature interlocks on purpose → works, interlock threshold at 32 deg C






→ Gun modulator could not be reset

Gun Water Flow Rate

Investigations by MIN and MKK2

• Final interlock reason found: Water flow rate too low, threshold at 9.5 l/min

Same Error Bit set due to Gun water temperature, water flow rate and water pressure (not monitored regularly)





- → Fixed on Wed around noon
- → Stable operation for rest of week

Plan for the week

TWAC beam time

- Optimize WP3 (increase gun gradient and optimize transverse focusing) + characterize trtansmission through alignment channel
- Generate WP4 (WP3 with compression in time via velocity bunching).
- Measure emittance at experimental location (wire scanner) to ease comparison with simulations.
- Continue tests of longitudinal wakefield effect (going off-axis in the alignment channel).
- Try to go down to 10 MeV/c to be closer to the beam available at PHIL.
- Try to improve transverse quality by starting with more charge and then collimate to 10 pC.

(Sorted by priority)

On Thursday evening: partial AA shift, i.e. preparing autonomous agents for overnight runs

Schedule

Week 38

Date	Shift Crew
18.09.	
19.09.	Thomas, Max
20.09.	Thomas, Max
21.09.	Thomas, Max
22.09.	Thomas, Max

Week dedicated to TWAC

If you want to learn or join the shift: please give the shift leader a call (BKR 2840 / SINBAD Box 2454)