





Pac Tech's electroless nickel gold (ENIG) UBM process failed on 5 of 7 CiS dummy wafers

OPTICAL MICROSCOPE PICTURES OF AFFECTED WAFERS

- First 7 AlSiCu wafers processed
- 2 wafers without failures
- 5 wafers show errors in UBM
- 12 unprocessed wafers (9 AlSiCu and 3 AlSi) go back to CiS




Overview after ENIG process




Zoomed views to pads either with missing or partial UBM after processing

Pac Tech's electroless nickel gold (ENIG) UBM process failed on 5 of 7 CiS dummy wafers


EXEMPLARY SEM PICTURES OF AFFECTED WAFER #14




Pad with poor UBM




Wafer#14



Pad with UBM




Few UBM islands only




Pad with thin UBM

70 nm residual layer found in SEM cross sectional view


SEM PICTURES OF A UNWETTED PAD ON WAFER#16



200 nm nitride
1 µm oxide
1.2 µm AlSiCu
200 nm nitride



Thin residual
passivation layer
70 nm SiO₂




Plasma etch

- was stopped too early
- badly adjusted

Oxide deposition badly
adjusted?

CiS second etch step resulted in discolored pads on both AlSiCu and AlSi wafers



MICROGRAPHS OF PAC TECH INCOMING QUALITY CONTROL



Affected pads:
50 to 70 %

UBM deposition tests failed in shorts and rough nickel surface


MICROGRAPHS OF PAC TECH UBM QUALITY CONTROL AFTER TEST PROCESS




- UBM growth also on metal lines → shorts
- Irregular bump growth → rough surface

Pads are also still affected by incomplete openings in the passivation layer


MICROGRAPHS OF PAC TECH UBM QUALITY CONTROL AFTER TEST PROCESS



Incomplete openings



Island like UBM growth



100 % of the pads are affected by failures