









Status at MPP

Markus Reif


Belle II PXD Workshop 21 January, 2020
























wooden structure for fixation














3D printed structure for easier plugging

wooden structure for fixation














3D printed structure for easier plugging

wooden structure for fixation

new adapter PCB currently designed





Test Stands





pxdtest12: • DHE-only setup

used for module characterization


pxdtest8: • DHE-only setup

DHE has problems with highspeed links

> was used for Philipps emergency-shutdown-mass-test

pxdtest9: •

- ladder-setup
- highspeed link problems
- ssd broke and was exchanged
- will be upgraded to DHH-setup







Module Situation





	Status	Quality
W04_OB1	tested (analog)	Class A
W05_IB	tested (analog)	Class A
W05_OF1	tested (digital)	Class A
W06_IB	probecard-tested (analog)	not classified
W06_IF	probecard-tested (analog)	not classified
W09_OF2	tested (digital)	Class C
W10_IF	tested (digital)	Class A
W10_OB1	tested (digital)	Class A
W11_IB	probecard-tested (analog)	not classified
W11_IF	probecard-tested (analog)	not classified
W11_OF1	tested (analog)	Class A
W12_OB1	tested (digital)	Class C
W37_OB1 (BEAST)	Kapton attached	not classified
W44_OB2	tested (analog)	Class A
W45_OF2	tested (analog)	Class A
W46_IB (BEAST)	Kapton attached not classified	

Summary			
Class A (>99%)	8		
Class B (>98%)	-		
Class C (<98%)	2		
To be tested	6		
Sum	16		

possible ladders				
	L1	L2		
Class A	1	3		
Class C		1		
Sum	1 (+2)	4		








Kapton Attachment







suspicious 'outrunners' on module W10_IF

- probably due to new charge of soldering tin (lower viscosity)
- no effects during module testing
- > one dummy module (looks good)
- > continue kapton attachment





Ladder Situation





Layer 1		Layer 2	
	Quality		Quality
L1_21	Class A	L2_42	Class B
L1_30	Class A	L2_43	destroyed
		L2_44	Class A
		L2_45	Class A
			Class A
		L2_47	Class A
		L2_48	Class A
		L2_49	Class A
		L2_50	Class A
		L2_51	Class A
		L2_52	Class A

Summary			
	Layer 1	Layer 2	
Class A	2	9	
Class B		1	

enough ladders to complete PXD





Summary & Outlook





Summary:

- have 8 Class A, 2 Class C and 6 untested modules
 - > 1 (+2) L1 Ladders and 4 L2 ladders
- have 2 L1 ladders and 10 L2 ladders

totally: 3 (+2) L1 ladders and 14 L2 ladders

Outlook:

- get cable tester running
- test remaining modules
- start ladder gluing when we have reasonable amount of modules









Thank

you!