



CMS Running Experience

Erik Butz

Kick-off Workshop of the Project

"Enabling Technologies for Silicon Microstrip Tracking Detectors at the HLLHC"



2013-02-28



The CMS Silicon Strip Tracker



- Largest silicon tracker ever built (active area $\sim 200 \text{ m}^2$)
- 5 m long, 2.5 m diameter
- First “all-silicon” central tracker
- Approx. 9.6 million electronic channels
 - 10 layers in barrel region
 - 4 Inner Barrel (TIB),
 - 6 Outer Barrel (TOB)
 - and 9 discs in the endcaps
- Analog readout




- Angular coverage down to 9° to the beam-pipe ($|\eta| < 2.5$)
- 4 layers (3 rings) contain stereo modules for 2-D hit reconstruction



Readout and Services


- tracker has 440 Front End Drivers (FEDs) to read out detector modules
- 356 control (token) rings to program the detector electronics



- 1944 power groups, 3888 HV channels
- two cooling plants to remove dissipated heat
 - 1st plant with leak rate close to zero
 - 2nd plant with low leak but with 5 closed lines

SS2 cooling plant leak rate

- in 2009 introduced overpressure on SS2 cooling in an accident
- caused an increase in leak rate in some cooling lines




2011

- pressure to the detector reduced (0.6-0.8 Bar reduction) → no change in module T
- CP pressure reduced from 9 to 7 bar and safety pressure switches were installed
- Pump running with Variable Frequency Driver: longer lifetime, smoother operation, no pressure glitches, vibrations (pump were replaced due to overheat)
- Bigger bypass valve installation to allow a smoother operation




Detector Status 2010 - 2013



- Major failures during operation
 - control ring in TIB (1 FED, 0.8 % of inner barrel) started showing non-standard behavior
 - few CCUs and power groups developed problems (groups of 6-12 modules)
 - some modules masked in loops with passive cooling to reduce heat load



Detector Status 2010 - 2013



- Major failures during operation
 - control ring in TIB (1 FED, 0.8 % of inner barrel) started showing non-standard behavior
 - few CCUs and power groups developed problems (groups of 6-12 modules)
 - some modules masked in loops with passive cooling to reduce heat load



Detector Control and Safety System

- TCS and TSS working reliably with close to zero downtime caused over three years of running
- Alarms with SMS to experts and Tracker DOC¹ for e.g. problems with cooling, dry gas, power supply trips,...



- In addition: SMS from DAQ, DQM in case of critical problems for data taking (but not detector safety)

¹DOC = detector on-call




Experience with shifts (short timeline)



- 2009: Tracker DOC + Tracker shifter at P5, responsible for monitoring and switching on HV
- mid-2010: no more shifters at P5, centrally attended operation BUT
 - 2 DOCs:
 - one daily monitoring (environment,...)
 - one coming to **P5 at start of every physics fill** to give green light for HV raising and check of DQM
- mid-2011: HV switch-on handed to central crew, DOC performing checks remotely (only one DOC)
- mid-2012: HV raising automated using semaphore, DOC performs daily monitoring



2012




- CMS with 93.6 % data taking efficiency (4.7% downtime, 1.7% deadtime)
- strip tracker caused 0.98% of downtime (21% of 4.7%)
 → $\sim 230 \text{ pb}^{-1} \text{ pb}$




Downtime length

Time to recover from TRK DAQ incidents during Stable Beams (2012)



Data losses from certification



- data loss from HV raising unavoidable due to safety considerations
 - high voltages are only raised when LHC declares beams to be *stable*
- very little data certified as bad (70.0 of 21790 pb⁻¹ = 3.2 ‰)



Data losses



Infrastructure failures

- over the three years of running had very few failures of infrastructure
- $O(10)$ failures of VME crate items (PS, Fans)
 - some times lucky to have them happen outside stable beams
 - time to fix can be 1/2 – 3 hours depending on circumstances
- few bigger problems with CAEN power supplies
 - exchange rate of PSUs below 1% per year, exchange done opportunistically
 - recently one CAEN mainframe had to be exchanged
 - done in < 2h



Improvements to operational procedures




- Several approaches to reduce data losses caused by the strip tracker
- reduce time needed to raise high voltage after the declaration of stable beams (next slides)
- make use of *soft error recovery* mechanism
- improvements in FED firmware
- speeding up of state transitions (hardware configuration, run starting/stopping, etc. . .)
- power supply recovery policy
 - during 2010-11 whenever a power supply went spontaneously **off**
 - at next run stop power supply switched back on and tracker reconfigured
 - 5 minutes (minus time needed for initial reason for stopping)
 - end of 2011: for single power supplies, no run stop, only recover after end of fill
 - trading redundancy in layout for data taking efficiency



HV raising

- high voltages are only raised when LHC beams are declared *stable*
- several steps to shorten time delay till HV is up
 - increased number of CAEN Mainframes: 4 \rightarrow 8 in early 2011
 - reduced time needed to raise HV from 5 to 1.5 minutes
- since 2012 the high voltages of the strip (and pixel) tracker are raised automatically at *stable beams*




- semaphore checks beam conditions 30 s before *stable beams* are declared
 - now takes ~ 1 minutes from declaration of stable beams to HV up
 - before ~ 1.5 -2 minutes with large outliers

→ further possible improvements:

- ways to allow raising before stable beams are declared
- shorten HV raising time

Soft Error Recovery


- The 'soft error recovery' is the standard way for the CMS DAQ to recover from SEU-like events.
 - subdetector detects 'soft error' and goes to *RunningSoftErrorDetected* state
 - cDAQ pauses the trigger and sends 'fix soft error' command to subdetector
 - subdetector 'fixes' problem and goes back to 'running' state
 - cDAQ sends *resync* and resumes triggers
- The strip tracker is using this mechanism to recover a control ring in the TIB layer 2
 - uses the redundant path (entering the control ring through channel B) which gets spontaneously reset during running.





Soft Error Recovery

- The 'soft error recovery' is the standard way for the CMS DAQ to recover from SEU-like events.
 - subdetector detects 'soft error' and goes to *RunningSoftErrorDetected* state
 - cDAQ pauses the trigger and sends 'fix soft error' command to subdetector
 - subdetector 'fixes' problem and goes back to 'running' state
 - cDAQ sends *resync* and resumes triggers
- The strip tracker is using this mechanism to recover a control ring in the TIB layer 2
 - uses the redundant path (entering the control ring through channel B) which gets spontaneously reset during running.






Soft Error Recovery




Time spent for Soft Error Recovery (only strip tracker part)
Time in RSED (FED 101)



- re-application of redundancy performed in 1-2 seconds
- CMS back to running state in $\ll 30\text{seconds}$




Complications for Recovery






Complications for Recovery






Complications for Recovery






Complications for Recovery






Complications for Recovery






Complications for Recovery



SEUs in general

- most features seen in the strip tracker to this date are **not** classic SEUs, i.e.
 - no clear radial dependence
 - no clear dependence on instantaneous luminosity
- There are some effects that occur predominately during collision runs
 - these manifest mostly on single APV readout chips
 - there is a pedestal of APVs with problems for many runs and
 - there is a slight increase of the number of affected APVs over the course of a run

Number of APVs with APVAddressError vs time





Extra Events



- Problem of extra events is caused by one or more modules starting to output data w/o a trigger associated with it
- Strip Tracker FED is a *capturing* device, i.e. if things looking like data are detected on a sufficient number of inputs, this is captured as an *event*
- will associate this to a trigger and ship it to CMS DAQ
 - one trigger too little available if real data comes
 - FED is stuck since it has data that it cannot ship out
- solved by sending FED to *out-of-sync* when this situation is detected
 - results in *resync* signal issued by CMS DAQ
- extra data is discarded and run can continue



FED Firmware



- FED firmware underwent several iterations during 2012
- some bugs were found and fixed,
- more importantly: iterative process to properly address various situations FEDs are exposed to **not** foreseen in original design
 - extra events (single or continuous)
 - missing events
 - resyncs under backpressure (i.e. CMS DAQ not accepting events)



Summary and Outlook



- CMS Strip Tracker running well also in its third year of more or less continuous operation
- operational procedures continuously improved over the last three years
- no big surprises *so far*
- several smaller and bigger problems have plagued us and caused our share of data-loss
- infrastructure failures easily contribute non-negligible amounts of lost data