


Status report uni Hamburg

Matteo Centis Vignali, Erika Garutti, Johannes Haller, Tobias Lapsien, Jennifer Sibille, Georg Steinbrück



Death of a module




- •Weird peak in the ADC spectra (with no fluorescence target) No full depletion?
- •Problems with the power connector
- Unexpected high leakage current
- •Tested the current behavior disconnecting the sensor from the HDI
- •No apparent damage in the sensor
- No clear cause of the death






Adapter for single chip modules


- Temperature stabilization
- •Humidity issue for low temperatures (maybe a hole in the protection cap helps?)
- Drawings submitted to the workshop







Command software for the X-ray test



We want also to include the psi46expert at some stage