



Last update 10.10.2011

10.10.2011 Additional 5 RU for Redundancy PS (WP34) were reserved in the „Power supplies“ cabinet
20.10.2011 RF-Cabinet rearranged