


BCM1F Status after Re-installation


Ringo Schmidt for the BRM group

BCM1F Re-installation

- Delay of 2 weeks due to a Pixel tracker cooling leak
- Successful test of all modules before installation
- Re-installation completed in 2 days after Easter
- Test of all channels after re-installation
- Fully operational




Test Pulse in each Channel











Baseline Stability



Baseline of the BCM1F Modules



Baseline Spectra




Test Pulse Spectrum



Further Investigations

- Characterisation of the system by means of a reference setup
- Analysis and comparison of the data taken last year
- Further development of the readout software
 - Selftrigger mode
 - Data publishing

Linearity



Signal to Noise Ratio

