Noise study of charge measuring system in PITZ



Cause and solutions for the 300kHz noise

