Contribution ID: 3 Type: not specified

X-ray Radiation Damage: Sensors

After a short introduction into radiation damage the measurements of the relevant parameters characterizing X-ray radiation damage will described, their impact on segmented p-n sensors discussed and some conclusions drawn.

Presenter: Prof. KLANNER, Robert (Universität Hamburg)